

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FN826
NW
> 1
1.132 mi.
5975 ft.

NYC DEPT OF SANITATION - A MALUMED
1824 SHORE PKWY BK-W-11
BROOKLYN, NY 11214

Site 5 of 8 in cluster FN

RCRA-VSQG
NY SWF/LF
NY LTANKS
NY Spills
FINDS
ECHO
NY MANIFEST

1000141005
NYD982741308

Relative:
Higher

Actual:
8 ft.

RCRA-VSQG:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: NYC DEPT OF SANITATION - A MALUMED
Facility address: 1824 SHORE PKWY BK-W-11
BROOKLYN, NY 11214-6607
EPA ID: NYD982741308
Mailing address: 58TH ST ROOM 404
WOODSIDE, NY 11377
Contact: Not reported
Contact address: 58TH ST ROOM 404
WOODSIDE, NY 11377
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: NYC SANITATION DEPT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC SANITATION DEPT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYC DEPT OF SANITATION - A MALUMED
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1999-07-08 00:00:00.0
Site name: NYC DEPT OF SANITATION - A MALUMED
Classification: Not a generator, verified

Date form received by agency: 1989-06-07 00:00:00.0
Site name: NYC DEPT OF SANITATION - A MALUMED
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: X001
. Waste name: WASTE OILS

Violation Status: No violations found

SWF/LF:

Name: NYCDOS SOUTHWEST BROOKLYN INCINERATOR
Address: 1824 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY 11214
Flag: INACTIVE
Region Code: 2
Phone Number: 7180000000
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Waste combustion - no energy recovery
Activity Number: [24EB9]
Active: No
East Coordinate: Not reported
North Coordinate: Not reported
Accuracy Code: Not reported
Regulatory Status: None
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

LTANKS:

Name: NEW YORK CITY DOS SOUTHWEST 11
Address: 1824 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0801016 / 2011-07-05
Facility ID: 0801016
Site ID: 396872
Spill Date: 2008-04-24
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: adzhitom
Referred To: NFA
Reported to Dept: 2008-04-24
CID: 77
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-04-24
Spill Record Last Update: 2011-07-05
Spiller Name: Not reported
Spiller Company: NYC DEPT. OF SANITATION
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: NYC DEPT OF SANITATION
Spiller Phone: (631) 586-4900
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 162113

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DEC Memo:

"6/2/08 bf: Sent ttf letter to: NYCDOS 125 Worth St., Room 823 New York, NY 10013 7-5-2011 The spill was originally assigned to Brian Falvey. After discussion with Brian Falvey, this spill # was transferred to Alex Zhitomirsky who is handling other spills at this site. According to LiRo report dated 4/6/2011, this spill involved a tank test failure of a gasoline UST located along the southeastern side of the garage. An unknown amount of gasoline was reportedly released to the surrounding soil. On October 2, 2009, Gemstar under the supervision of LiRo began the closure activities for two 4,000-gallon USTs, Tank No.'s 4 and 5. Six sidewall samples and four bottom samples were collected from the excavation. Groundwater was not encountered in the excavation; therefore, no groundwater samples were taken. VOCs were detected in in several of the samples; however, the compounds were detected below NYSDEC TAGM 4046 criteria. SVOCs were detected in in several of the samples, however, SVOC exceedances were only observed in one sample. The compound detected above NYSDEC TAGM 4046 criteria was a polycyclic aromatic hydrocarbon(PAH), which is typically found in urban fill material. Based upon the absence of visual evidence of petroleum leakage and any significant VOC/SVOC detection, no further soil investigation was recommended for this site. Based on this information this spill # is closed and e-mail is sent to LiRo/F. Ashkan/V. Brevdo. AZ "

Remarks: "initial tank test failure. isolate tank and tank will be tested alone."

All TTF:

Facility ID: 0801016
Spill Number: 0801016
Spill Tank Test: 2453597
Site ID: 396872
Tank Number: 5
Tank Size: 4000
Material: 0009
EPA UST: Not reported
UST: False
Cause: 00
Source: 00
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:

Site ID: 396872
Operable Unit ID: 1153839
Operable Unit: 01
Material ID: 2144614
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Name: NYC DDC BROOKLYN W 11TH G
Address: 1824 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0001699 / 2003-11-14
Facility ID: 0001699
Site ID: 194530

Spill Date: 2000-04-25
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 2000-05-10
CID: 366
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-05-10
Spill Record Last Update: 2003-11-14
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 162113
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ROMMEL refer to spill 0001700"
Remarks: ""

All TTF:
Facility ID: 0001699
Spill Number: 0001699
Spill Tank Test: 1525573
Site ID: 194530
Tank Number: 2
Tank Size: 1000
Material: 0015A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 194530

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 823520
Operable Unit: 01
Material ID: 289914
Material Code: 0015

Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BROOKLYN WEST 11 DOS -DDC
Address: 1824 SHORE PARKWAY
City, State, Zip: BROOKLYN, NY
Spill Number/Closed Date: 0001700 / 2014-10-16
Facility ID: 0001700
Site ID: 194531
Spill Date: 2000-04-25
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 2000-05-10
CID: 366
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-05-10
Spill Record Last Update: 2014-10-16
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 162113
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL see also spill 0001699 10/14/04 The spill was reassigned to Rashid Ahmed. 8/30/2005 Reviewed a Monitoring Report received on August 8, 2005. The report presents groundwater monitoring data. The report states that contamination in wells MW-11R and MW-18R has increased when compared to previous quarter but lower than historical levels. LiRo has proposed placing an ORC sock in monitoring well MW-18R. LiRo recommends continuing the monitoring plan at this site. The Department concured with these proposals. AZ 3-17-2009 An e-mail was sent to B. Morrissey (Roux): What's the status of this site? We have not received updates/reports since 2005. AZ 3-23-2009 Response was received from Craig Werle(Roux): We have no record of this spill

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

number AZ 3-24-2009 An e-mail was sent to DDC/Roux: This spill was discussed at the meeting with Greyhawk on 12/22/06. The spill is related to a failed hoist oil tank at NYC facility. This spill should be investigated. AZ 6-9-2011 Received a proposal from LiRo for the advancement of 3 soil borings around the perimeter of UST#13 which is located adjacent to the garage building and the Auto Repair Shop along Bay 41st Street. These borings will help determine subsurface conditions around the UST and this and its relationship to this spill number. This proposal was approved via e-mail. AZ 10-15-2014 Reviewed a spill closure report dated May 8, 2014. The report stated that this spill reportedly involved a tank test failure of a hoist oil UST. The UST was reportedly closed and removed in 2000. Three confirmatory borings were completed in March 2013. The results show no detections of VOCs or SVOCs in all six samples collected. In the sample from 9 to 10 feet bgs at LSB-01, there were detections of SVOCs totaling 2,120 PPB. This sample was collected in a zone described by Liro's geologist as fill. Temporary well points were sampled on March 8, 2013. The results show low level exceedances of NYSDEC AWQSGV for VOC in groundwater in two wells. (39 ppb and 18 ppb). LiRo recommended that Spill 0001700 be closed. DEC concurred."

Remarks:

All TTF:

Facility ID: 0001700
Spill Number: 0001700
Spill Tank Test: 1525574
Site ID: 194531
Tank Number: 3
Tank Size: 1000
Material: 1096A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 194531
Operable Unit ID: 823521
Operable Unit: 01
Material ID: 289915
Material Code: 1096A
Material Name: hoist oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: NYC DEPT SANITATION
Address: 1824 SHORE PARKWAY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0602085 / 2006-09-28
Facility ID: 0602085
Facility Type: ER
DER Facility ID: 162113
Site ID: 364483
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2006-05-25
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 2006-05-25
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-25
Spill Record Last Update: 2006-09-28
Spiller Name: JAY SHAW
Spiller Company: NYC DEPT SANITATION
Spiller Address: 1824 SHORE PARKWAY
Spiller Company: 001
Contact Name: JAY SHAW
DEC Memo: "5/26/2006 - No answer at Sanitation 5/30/06- DEC Piper spoke w/ Jay Shaw at DSNY. Leak is continuous in a 2500 gal UST Ethanol . It is contained in the interstitial space of the doublewall fiberglass tank. CSL sent to NYC Dept. Of Sanitation 125 Worth St., Rm. 823 Manhattan, NY 10013 Attn: Chief of Equipment 7/3/06- DEC Piper received letter fro mSanaitaiton stating tank was pumped and lock installed on Fill box. spoke w/ AI at Sanitation. He will talk to engineering and his supervisor, Neil Gallager and respond to DEC. 9/28/06- DEC Piper spoke w/ sanitation regarging status. As per Neil, tank is still dry and are trying to replace it under warranty. Tank is locked out, no release to subsurface. Spill is closed."
Remarks: "LEAKING ETHONOL TANK: IS CONTAINED"
Name: GARAGE
Address: 1824 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1009225 / 2010-11-29
Facility ID: 1009225
Facility Type: ER
DER Facility ID: 162113
Site ID: 442752
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2010-11-26
Investigator: RMPIPER
Referred To: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Reported to Dept: 2010-11-26
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-11-26
Spill Record Last Update: 2010-11-29
Spiller Name: CALLER
Spiller Company: UNKNOWN
Spiller Address: 1824 SHORE PARKWAY
Spiller Company: 999
Contact Name: CALLER
DEC Memo: "DEC Piper responded to site. Spill was from a broken valve at the dispenser hose. Spill to concrete and drain. Sand placed on ground by sanitation. AARCO on scene cleaning and pumping drain. Cleanup completed at 1300hrs. Spill closed. "
Remarks: "sadh around area to contain. possibly went down water drain."

All Materials:

Site ID: 442752
Operable Unit ID: 1193252
Operable Unit: 01
Material ID: 2188619
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 175.00
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

FINDS:

Registry ID: 110009476398
Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110009476398

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000141005
Registry ID: 110009476398
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110009476398>
Name: NYC DEPT OF SANITATION - A MALUMED

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Address: 1824 SHORE PKWY BK-W-11
City,State,Zip: BROOKLYN, NY 11214

NY MANIFEST:

Name: NEW YORK CITY DEPARTMENT OF SANITATION
Address: 1824 SHORE PKWY BK-W-11
City,State,Zip: BROOKLYN, NY 11214-6607
Country: USA
EPA ID: NYD982741308
Facility Status: Not reported
Location Address 1: NELLIE BLY PARK
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11220
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD982741308
Mailing Name: NEW YORK CITY DEPARTMENT OF SANITATION
Mailing Contact: ED BRESCIA
Mailing Address 1: 1824 SHORE PARKWAY
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182666599

NY MANIFEST:

Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: CTD021816889
Trans2 State ID: Not reported
Generator Ship Date: 06/17/2009
Trans1 Recv Date: 06/17/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/17/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982741308
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: CTD002593887
TSDF ID 2: Not reported
Manifest Tracking Number: 000133304UIS
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	201.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported